

## Under Review Notification

**Raised By:** NCR14-3521, PAR14-331, etc.

**Product #:** D350-578, D407-559, D117-840

**Date:** 15.02.23

**Product Name:** Bearpaws

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review		
D4011-1	D4011 Rev. B	N	N	N	N	N	N	N	15-532	Update stock w/ released drawing
D4011-3	D4011 Rev. B	N	N	N	N	N	N	N	15-532	Update stock w/ released drawing
D4011-5	D4011 Rev. B	N	N	N	N	N	N	N	15-532	Update stock w/ released drawing
D4012-1	D4012 Rev. B	N	N	N	N	N	N	N	15-532	Update stock w/ released drawing
D4799-1	D4799 Rev. B	N	N	N	N	N	N	N	15-535	Update stock w/ released drawing

**Description of Issue:**

Customer complaints about the Bearpaw rotating too easily around the skidtube and about the Cushion rotating around the skidtube and not returning to its original position. Per NCR14-3521, PAR14-331 and PAR14-368.

**Distribution:**

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Planning Manager

Program Manager